

## State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

Out going 50470099

MICHAEL R. STYLER Executive Director JOHN R. BAZA Division Director

March 10, 2008

Dr. James W. Patten Red Leaf Resources, Inc. 6985 Union Park Center, Suite 375 Cottonwood Heights, Utah 84047

Subject: <u>Deficient Notice of Intention to Commence Small Mining Operations, Red Leaf</u>
Resources, Inc., RLR Site #9 S/047/0099, Uintah County, Utah

Dear Dr. Patten:

The Notice of Intent to Commence Small Mining Operations (NOI), received by the Division February 25, 2008, is incomplete. The following information is required:

- 1. On Page 3 of the Notice, the name of Red Leaf is misspelled as "Red Lead" under the ownership of minerals section.
- 2. On the first page of the attached narrative, the title lists a mineral lease number that is different from the one shown in item 1 of the narrative. Please correct them to refer to the same lease number.
- 3. On the Operations Map, Figure 2.0, show the location of the access road leading from the county road to the mining operation.
- 4. Label the county road on the operations map with its name as described in the narrative description of the mining operation.

Please submit replacement pages for your NOI with correct information on them.

Reclamation surety is required to be posted by all mining and exploration operations. The surety amount for this site is \$20,700.00 escalated for three years, or \$22,300 escalated for five years. You must contact Jed Pearson, Division Minerals Surety Coordinator to complete the reclamation surety and submittal of the reclamation contract. He can be reached at (801) 538-5382 or <a href="mailto:bondcoordinator@utah.gov">bondcoordinator@utah.gov</a>.

Page 2 James W. Patten S/047/0099 March 10, 2008

In reply, please refer to file number S/047/0099. Thank you for your cooperation.

Sincerely,

Susan M. White

Mining Program Coordinator Minerals Regulatory Program

Juan M. White

SMW:jcm:pb Task ID# 2253

c: John Blake, SITLA

P:\GROUPS\MINERALS\WP\M047-Uintah\S0470099-RLR9\final\deficient-ltr9.doc